

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/Ala Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-019180**Date Inspected:** 31-Dec-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes	No N/A
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes	No N/A
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes	No N/A
Approved Drawings:	Yes No N/A	Approved WPS:	Yes	No N/A
		Delayed / Cancelled:	Yes	No N/A
Bridge No:	34-0006	Component:	Tower Components	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 11

This QA Inspector randomly observed no welding related work in progress in Bay 11.

ZPMC workers performed match drilling operations of approximately 20mm holes from the outside at the top of east tower, lift 5, skin C and skin D, positioned vertically and 26mm holes from the inside at the bottom of the grillage area of north and west towers, lift 5, skin A, positioned horizontally, as well as at the bottom of skin A connection plates. Other workers were performing match drilling operations of 30mm holes in various tower splice plates. See photo below.

Bay 10

This QA Inspector randomly observed no apparent work in progress in Bay 10.

OBG Trial Assembly Area

This QA Inspector randomly observed no apparent work in progress in the OBG Trial Assembly Area.

Heavy Dock

This QA Inspector randomly observed no apparent work in progress on the Heavy Dock.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Micheal Ng, 159-2184-5703, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet, George
----------------------	----------------

Quality Assurance Inspector

Reviewed By:	Riley, Ken
---------------------	------------

QA Reviewer
